


# PUBLIC LAND CORNERS

SPRINGFIELD  
 SURVEY FILE

WYERHAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 2 W  
 SECTION 8 CORNER SW 1/16 "LL"  
 COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
44" Fir	S 79 E	17.0	-----	X	X	-----
18" Chinquapin	S 89 W	26.5	Hosford	X	X	-----

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal -- Logging Debris.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 60 E ON MINUS (-) 26 %

NORTH: Level 25' then descend. '59 logging to West, old growth to East

SOUTH: - 33% old growth to East and West.

EAST: - 19% 20' then slope increases. Old growth North and South

WEST: 4% 30' then descend.

FROM CORNER -

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Allen M. Cheney DATE: 7/29/59  
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF

ASSISTED BY:

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

DATE: \_\_\_\_\_

ACCESSORIES:

BEARING-	LINKS-	FEET-

Hosford SURVEY RECORD  
 DATE: 1958

PRESENT CONDITION:

<u>1 1/2" X 3/8" Iron Pipe</u>		<u>Found</u>
<u>12" Hemlock S 55 E</u>	<u>26.3'</u>	<u>Scribed SW 1/16 S8 BT 253</u>
<u>18" W Chinquapin S88W</u>	<u>26.6'</u>	<u>Scribed SW 1/16 S8 BT 253</u>

CORNER SET: Iron pipe set by Hosford Survey MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
<u>S 53 E</u>	<u>26.3</u>	<u>Hosford</u>	<u>Measured to face.</u>
<u>S 89 W</u>	<u>26.6</u>		<u>Measured to face.</u>

PAGE 1

27

CS 53/112-11