


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 25S RANGE 2W
 SECTION 10 CORNER E 1/4
 COUNTY Douglas OREGON

GLO SURVEY RECORD

DATE: 1900
 CORNER Dogwood Post

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
40" Fir	N 52 W	40	26.4	48" Fir - Scar of single large face.
13" Cedar	S 64 E	54	35.6	14" Cedar - Faces burned away.

SURVEY RECORD
 DATE: _____

PRESENT CONDITION: _____

CORNER SET: 2" x 4' stake as found MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 52 W	26.0	GLO	
S 65 E	35.6	GLO	To center of tree.

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG.B.T.	"W" NAIL	PLATE	BRASS DISC
36" Cedar	S 2 E	14.0	-	X	X	-
48" Fir	N 53 W	25.8	X	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Sala
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) N 80 E ON MINUS (-) 68 %

NORTH: - 4% 65' Draw C - SE Logged
 SOUTH: + 4% Residual Fir to East - old growth to West
 EAST: E - 60% 500' plate on 48" Fir stump on East side of dirt road.
 WEST: + 60% Logged to North - Old growth to South.

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Glen McCreaney DATE: March 27, 1960
ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY: William Wilt

COPIES SENT TO: _____

CS 53/112-12