

PUBLIC LAND CORNERS


SPRINGFIELD
 SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 2 W

SECTION 10 CORNER SW

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1900

CORNER Stone

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found Under 46" Fir blowdown

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
48" Fir	N 44 E	17	11.2	56" Fir-Upper & Lower Cat Faces Visible
20" Fir	S 29 E	75	49.5	24"x5' Fir Shell-Scribed "BT" Visible
14" Fir	S 33 W	34	22.4	Gone
12" Fir	N 35 W	40	26.4	14" Fir-Upper & Lower Cat Faces Visible

County SURVEY RECORD
 DATE: 1948

PRESENT CONDITION:

Found: Stone & NE and NW BTs
 Marked New:

30" Fir S5W 38.2' 36" Fir Stump-Bark Scribing Visible

30" Fir S45E 50.0' 42" Fir " " "

CORNER SET: Stone as found under fir blowdown MAG. DECL.: 20°

Drove Maple stake into top of log over stone.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-
N40E	11.2	GLO
S25E	46.5	"
N38W	26.4	"
S5W	38.8	CS
S33E	44.2	"

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
56" Fir	N 37 E	10.0	GLO	X	X	--
42" Fir	S 33 E	44.0	CS	X	X	--
12" Hemlock	S 3 W	18.1	--	X	X	--
14" Fir	N 39 W	25.8	GLO	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Oregon Grape

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 80 W ON MINUS (-) 50 %

NORTH: + 8% Through Old Growth

SOUTH: 2% for 30' thru -50%-Logged-Residual trees

EAST: + 28% for 30' thru +50% Old growth to North and South

WEST: - 50% for 40' thru slope increases. Along cutting line-logged to South-old growth to North

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Alan McCreaney DATE: 2/11/60
 ENGINEER - SURVEYOR

ASSISTED BY: William Wilt

UNDER THE SUPERVISION OF:

COPIES SENT TO:

CS 53/112-15

15-