


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 2 W
 SECTION 12 CORNER Q W 1/6
 COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: _____
 CORNER _____

ACCESSORIES:

	BEARING-	LINKS-	FEET-

Hosford **SURVEY RECORD**
 Post DATE: 1953-58

16" Cedar N 50° E 16.9
 18" Cedar S 70° W 29.6

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION: _____
 Hem
 Green - scribed
 Green - scribed

CORNER SET: Post by Hosford MAGNETIC DECLINATION: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
N 50° E	17.0	Hosford
S 70° W	29.8	Hosford

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. BOX	"W" NAIL	PLATE	BRASS DISC
18" Cedar	N 52° E	16.4	Hosford	x	x	
20" Cedar	S 71° W	29.6	Hosford	x	x	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Sisal, decayed logs
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) N 10° E ON MINUS (-) 40 %

FROM CORNER -
 NORTH: -40%, approximately 250' to Rock Creek
 SOUTH: -10% Current logging to West. Logged to East
 EAST: -40%, Approximately 200' to Rock Creek
 WEST: Level 50' -10%. Timbered to North, current logging to South

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Glenn McChesney
 ENGINEER - SURVEYOR

DATE: 1-30-58

UNDER THE SUPERVISION OF:

ASSISTED BY: _____

COPIES SENT TO: _____

CS 53/112-16

61