

PUBLIC LAND CORNERS


SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 2 W

SECTION 12 CORNER W 1/16 "G"

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: _____

CORNER _____

ACCESSORIES:

BEARING-	LINKS-	FEET-

Hosford SURVEY RECORD
DATE: 1953

3" Hemlock Post
16" Cedar - N 50° E - 16.9'
20" Cedar - S 70° W - 29.6'

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION: _____

Found
18" cedar - scribed
20" Cedar - scribed

CORNER SET: Found post in place

MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
N 50° E	17.0	HOSFORD
S 70° W	29.8	"

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
18" Cedar	N 52° E	16.4	HOSFORD	X	X	
20" Cedar	S 71° W	29.6	"	X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) _____ %

NORTH: _____

SOUTH: _____

EAST: _____

WEST: _____

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Allen McCleary DATE: 1/30/58
ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF: _____

ASSISTED BY: _____

COPIES SENT TO: _____

SEAL

PAGE 3

CS 53/112-17

02