


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH



TOWNSHIP 25 S RANGE 2 W
 SECTION 14 CORNER G N 1/16
 COUNTY Douglas OREGON

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
32" Fir	S 59° W	22.4		x	x	
18" Fir	N 9° W	22.3		x	x	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) N 70° W ON MINUS (-) 10 %

NORTH: Level 25' then -50% Timbered. Will be logged to East 1958
SOUTH: -3% 10'; / 35% 110 to plate on fir south side rock road
EAST: / 15%. Logged to South, will be logged to North 1958
WEST: -10%. Timbered to North and to South

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Sharon M. Chesney DATE: 1-30-58
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

DATE: _____
 CORNER _____

ACCESSORIES:

BEARING-	LINKS-	FEET-

V. Hosford **SURVEY RECORD**
 DATE: 1953-1958

PRESENT CONDITION:
Scribed, broken
Green. Scribed 1/16 S13 PS253 BT
Dead. Scribed 1/16 S14 PS253 BT

3" Hem Post
10" Hem - N 45° E 5.4
12" Hem - N 64° W 18.6

CORNER SET: Post set by Hosford MAGNETIC DECLINATION: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-
<u>N 45° E</u>	<u>5.4</u>	<u>Hosford</u>
<u>N 64° W</u>	<u>18.6</u>	<u>Hosford</u>

CS 53/112-19

81