


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 2W
 SECTION 14 CORNER S $\frac{1}{4}$
 COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1900
 CORNER Stone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
10" Hemlock	N42W	18	11.8	12" Hemlock - face scars
9" Hemlock	S3W	32	21.1	16" Hemlock - face scars

SURVEY RECORD
 DATE: _____

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found - Marked "1"

PRESENT CONDITION: _____

CORNER SET: Stone set by GLO 1900 MAG. DECL.: 19°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N44W	11.8	GLO	12" Hem
S4W	21.1	GLO	16" Hem

ACCESSORIES ADDED THIS DATE: _____

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
16" Hemlock	S4W	20.1	X	X	X	--
46" Hemlock	N39W	18.8	--	X	X	--

IDENTIFIED ON PHOTO: _____

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Bracken - Moss

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) %

FROM CORNER -

NORTH: - 33% 70' old growth

SOUTH: + 51% old growth

EAST: + 10% 110' ascent steepens - old growth

WEST: - 5% 50' then level - old growth

WORK DONE FOR W. T. CO.: _____

FIELD NOTES IN BOOK: _____

BY: Glen McChesney DATE: 8/17/59

~~ENGINEER - SURVEYOR~~

ASSISTED BY: _____

COPIES SENT TO: _____

UNDER THE SUPERVISION OF: _____

SEAL

PAGE 3

33

CS 53/112-23