

# PUBLIC LAND CORNERS


SPRINGFIELD  
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 2W

SECTION 20 CORNER S $\frac{1}{2}$

COUNTY Douglas OREGON



**GLO SURVEY RECORD**

DATE: 1900  
CORNER Stone

**ACCESSORIES:**

	BEARING-	LINKS-	FEET-
14" Fir	N25E	67	44.2
6" Fir	S48E	54	35.6

SURVEY RECORD  
DATE: \_\_\_\_\_

**PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)**

Found Stone marked "1/2"

PRESENT CONDITION: \_\_\_\_\_

CORNER SET: Stone as found

MAG. DECL.: 20°

**BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:**

BEARING-	FEET-	SURVEY-	
N26E	43.7	GLO	Distance to face
S51E	34.4	GLO	Distance to face

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
12" Fir	S9E	7.3	--	X	X	--
4" Fir	N50W	13.3	--	X	X	--

IDENTIFIED ON PHOTO:

**INFORMATION ON LOCATION OF CORNER AS NOW SET:**

GROUND COVER: salal and ocean spray

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S45E ON MINUS (-) 43 %

NORTH: + 30% old growth to East and West

SOUTH: - 35% 30' then down over cliff. Approx. 230' to Rock Creek Road.

EAST: - 22% Approx. 340' to Rock Creek Road

WEST: + 16%

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Blair McChesney DATE: September 9, 1959

~~ENGINEER - SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL PAGE 3

CS 53/112-26

35