

PUBLIC LAND CORNERS


SPRINGFIELD SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 2W

SECTION 20 CORNER SE

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1900

CORNER Stone

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

No trace - probably destroyed by old logging.

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
10 Fir	N35E	56	37.0	18" White Fir - 2 cat faces not opened.
11" Cedar	S45E	10	6.6	22" Red cedar - cat face
48" Fir	S13W	25	16.5	48" Fir stump - scribing visible.
14" Fir	N57W	71	46.9	24" White Fir snag - 2 cat faces

SURVEY RECORD

DATE:

PRESENT CONDITION:

Found in field

18" Red Cedar

scribed "S20 253 BT"

see page 2

CORNER SET: Found 1 1/2" galvanized pipe - o.k. for distance MAG. DECL.: 20°

and bearing

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N34E	37.0	GLO	Distance to face
S45E	6.6	GLO	Distance to face
S13W	17.7	GLO	Distance to face
N57W	45.5	GLO	Distance to face

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
18" White Fir	N34E	36.2	X	X	X	--
28" Red Cedar	S40E	6.0	X	X	X	--
22" x 18" Red Cedar Snag	S3E	21.0	--	X	X	--
18" Red Cedar	West	33.2	Hosford	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Fern, Hazel, Salmonberry, Blue huckleberry

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
North

SLOPE FACES (GIVE BEARING IN DEGREES) 64 % ON MINUS (-)

FROM CORNER | NORTH: - 64% 12' to center Cr. C-N65W - plate on 48" fir South edge of rock road
"150' S SE Cor. Sec. 20"
+ 24% 25' then along West side of creek
SOUTH: - 64% 12' center Cr. C-N10W
EAST: + 15% 10' then - 18% 65' Cr. C-SW
WEST:

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Alan McCheyney DATE: September 9, 1959

~~ENGINEER - SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL PAGE 3

98

CS 53/112-27