


SPRINGFIELD
 SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH



TOWNSHIP 25S RANGE 2W

SECTION 30 CORNER SE

COUNTY Douglas OREGON

GLO SURVEY RECORD

DATE: 1900

CORNER Stone

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found with notches per GLO notes

ACCESSORIES

	BEARING-	LINKS-	FEET-	
12" Chinquapin	N36E	35	23.1	14" Chinquapin - face rotted
9" Chinquapin	S44E	32	21.1	12" Chinquapin - scribing visible - face rotted
8" Chinquapin	S13W	41	27.1	12" Chinquapin - cat faces - not opened
7" Fir	N12W	51	33.7	22" Fir - cat faces not opened

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: Stone set by GLO

MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N37E	22.7	GLO	Distance to face - 14" Chinquapin
S44E	21.6	GLO	Distance to face - 12" Chinquapin
S13W	27.1	GLO	Distance to face - 12" Chinquapin
N11W	33.7	GLO	Distance to face - 22" Fir

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
18" Fir	N79E	13.0	-	X	X	-
22" Fir	N11W	32.5	X	X	X	-
9" Hem	S4E	35.5	-	X	X	-
22" Fir	S78W	37.5	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Sisal

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) %

Corner is on narrow North-South spur ridge - slopes South

NORTH: ---

SOUTH: ---

EAST: ---

WEST: ---

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Glen McCheesney
 ENGINEER - SURVEYOR

DATE: August 20, 1939

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

PAGE 3

32

CS 53/112-45