


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 2W
SECTION 30 CORNER E $\frac{1}{2}$
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1900
CORNER Stone

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found as described GLO notes

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
12" Fir	S69E	48	31.7	28" white fir - cat faces
30" Fir	N55W	128	84.5	38" fir - scribing visible upperface

SURVEY RECORD
DATE:

PRESENT CONDITION:

CORNER SET: Stone set by GLO MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
S71E	33.3	GLO	Distance to face - 28" W. Fir - tree leans away from corner.
N56W	82.2	GLO	Distance to face - 38" Fir

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
28" White Fir	S71E	33.2	X	X	X	-
10" Red Cedar	N58W	19.5	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Vine Maple

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) Level ON MINUS (-) %

NORTH: 60' to old rock road

SOUTH: across creek bottom

EAST: across creek bottom

WEST: Level 50' then up steep bank to rock road

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Glen McClesney DATE: August 26, 1959
ENGINEER - SURVEYOR

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL PAGE 3

18

CS 53/112-46