


PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 2W

SECTION 36 CORNER N 1/L

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1900
 CORNER Stone

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found as described in field notes.

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
1 1/2" Fir	N65W	33	21.8	22" Fir - Scribing Visible on upper face.
1 1/2" Fir	S61W	33	21.8	2 1/2" Fir - Scars visible.

SURVEY RECORD

DATE: _____

PRESENT CONDITION: _____

CORNER SET: Original stone in place MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-
N63W	21.8	GLO
S60W	21.8	GLO

PAGE 1

ACCESSORIES ADDED THIS DATE: _____

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
40" FIR	S 86 E	6.0	--	X	X	--
38" FIR	N 81 W	16.8	--	X	X	--

IDENTIFIED ON PHOTO: _____

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: VINE MAPLE

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) SOUTH ON MINUS (-) 30 %

NORTH: + 25% 250' R/W OLD GROWTH

SOUTH: - 30% " "

EAST: Level 20' " "

WEST: - 5% " "

WORK DONE FOR W. T. CO.: _____

FIELD NOTES IN BOOK: _____

BY: John M. Orange DATE: 6/2/59

~~ENGINEER - SUPERVISOR~~

UNDER THE SUPERVISION OF: _____

ASSISTED BY: _____

COPIES SENT TO: _____

SEAL PAGE 3

CS 53/112-47.

42