


SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 3 W
SECTION 24 CORNER SW
COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1943
CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found

ACCESSORIES:

38" Fir	BEARINGS-	LINKS-	FEET-	
Old Bus!	N 11 E	34	22.4	38" Fir - Scar
36" Fir	S 42 E	80	52.8	40" Fir - Scar
12" Yew	S 45 W	10	6.6	12" Yew - Scribing Visible
30" Hemlock	N 26 W	62	40.9	36" Hemlock Original Scribing Visible
New Set:				
40" Fir	S 51 W	72	47.5	40" Fir - Scar

SURVEY RECORD
DATE:

PRESENT CONDITION:

CORNER SET: Post as set by 1943 GLO Survey MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
N 11 E	22.4	1883-1943	38" Fir
S 42 E	52.8	" "	40" Fir
S 45 W	6.6	" "	12" Yew
N 26 W	40.9	" "	36" Hemlock
S 50 W	47.5	1943	40" Fir

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
38" Fir	N 10 E	22.0	X	X	X	-
12" Hemlock	S 10 E	15.8	-	X	X	-
12" Yew	S 47 W	6.3	X	X	X	-
36" Hemlock	N 27 W	39.5	X	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Open Old Growth

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 75 E ON MINUS (-) 8 %

FROM CORNER -

NORTH: -3%

SOUTH: 4%

EAST: -8%

WEST: 11%

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: G. L. McChesney DATE: 5/5/59
~~ENGINEER SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

PAGE 3

CS 53/113-2