


SPRINGFIELD  
**SURVEY FILE**

**PUBLIC LAND CORNERS**

WEYERHAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH



TOWNSHIP 25 S RANGE 3 W  
 SECTION 26 CORNER " G "  
 COUNTY Douglas OREGON

GLO SURVEY RECORD			PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)		
CORNER DATE:					
ACCESSORIES:					
BEARING-	LINKS-	FEET-			
County	SURVEY RECORD	DATE:	PRESENT CONDITION:		
		1948			
1" Iron Pipe			Found		
12" Hemlock N 46 3/4 W	3.7'		12" Hemlock Scribing Visible		
20" Hemlock N 83 3/4 E	47.4"		20" Hemlock Scar		

CORNER SET: 1" Iron Pipe set by 1948 MAG. DECL.: 20°  
 County Survey

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:			
BEARING-	FEET-	SURVEY -	
N 46 W	3.7	1948	12" Hemlock
N 83 E	45.8	"	20" Hemlock

ACCESSORIES ADDED THIS DATE: \_\_\_\_\_ MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
12" Hemlock	N 49 W	3.1	CS	X	X	-
40" Inc. Cedar	S 85 E	28.3	-	X	X	-

IDENTIFIED ON PHOTO:

**INFORMATION ON LOCATION OF CORNER AS NOW SET:**

GROUND COVER: \_\_\_\_\_  
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
 SLOPE FACES (GIVE BEARING IN DEGREES) S 50 E ON MINUS (-) 28 %

FROM CORNER -  
 NORTH: 10%  
 SOUTH: -10%  
 EAST: -20%  
 WEST: 14%

WORK DONE FOR W. T. CO.: \_\_\_\_\_ FIELD NOTES IN BOOK: \_\_\_\_\_

BY: Shawn McCherry DATE: 5/5/59  
 ENGINEER - SURVEYOR

ASSISTED BY: \_\_\_\_\_

COPIES SENT TO: \_\_\_\_\_

UNDER THE SUPERVISION OF: \_\_\_\_\_

CS 53/113-3