4

SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 3W

SECTION 24 CORNER "B"

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

County SURVEY RECORD

DATE: 1948

3/4" Iron Pipe -	Found
24" Hemlock - ~~N 20½~~ E - 45.0'	26" Hemlock - Scribing Visible
20" Hemlock - ~~S 14½~~ E - 12.2'	20" Hemlock " "

PRESENT CONDITION:

CORNER SET: Pipe set by County Survey 1948 MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 20 E	44.1	CS	26" Hemlock
S 17 E	12.2	CS	20" Hemlock

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
60" Fir	N 63 W	14.2	-	X	X	-
20" Hemlock	S 18 E	11.9	CS	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 75 E ON MINUS (-) 15 %

FROM CORNER -

NORTH: -2% Virgin Timber

SOUTH: +5% "

EAST: -13% "

WEST: +20% "

WORK DONE FOR W. T. CO.:

BY: Glen McChesney ~~ENGINEER - SURVEYOR~~ DATE: 5/5/59

ASSISTED BY:

COPIES SENT TO:

FIELD NOTES IN BOOK:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/113-4