


6

SPRINGFIELD  
 SURVEY FILE

# PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 3 W  
 SECTION 24 CORNER S 1/4  
 COUNTY Douglas OREGON



**GLO SURVEY RECORD**

DATE: 1943  
 CORNER Brass Cap

PRESENT CONDITION - (DESCRIBE FULLY -  
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)  
Found

**ACCESSORIES:**

	BEARING-	LINKS-	FEET-	
<u>56" Fir</u>	<u>N 84 1/2 W</u>	<u>70</u>	<u>46.2</u>	<u>58" Fir Scribing Visible</u>
<u>20" Red Cedar</u>	<u>S 5 W</u>	<u>22</u>	<u>14.5</u>	<u>20" Red Cedar - Scribing Visible</u>

SURVEY RECORD  
 DATE:

PRESENT CONDITION:

CORNER SET: By proportional measurement by MAG. DECL.: 20°  
1943 GLO Survey

**BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:**

BEARING-	FEET-	SURVEY-	
<u>N 86 W</u>	<u>44.1</u>	<u>1943</u>	<u>58" Fir</u>
<u>S 3 W</u>	<u>13.3</u>	<u>1943</u>	<u>20" Red Cedar</u>

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG.B.T.	"W" NAIL	PLATE	BRASS DISC
<u>20" Red Cedar</u>	<u>S 3 W</u>	<u>13.0</u>	<u>1943</u>	<u>X</u>	<u>X</u>	<u>-</u>
<u>20" Red Cedar</u>	<u>N 55 E</u>	<u>6.2</u>	<u>-</u>	<u>X</u>	<u>X</u>	<u>-</u>

IDENTIFIED ON PHOTO:

**INFORMATION ON LOCATION OF CORNER AS NOW SET:**

GROUND COVER: Small Hemlock

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 55 E ON MINUS (-) 15 %

NORTH: -15% Virgin Timber

FROM CORNER 1

SOUTH: Level 20' - 15% " "

EAST: Level 15' -25% " "

WEST: 19% 60'

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Alan M. Cheney DATE: 5/5/59  
ENGINEER-SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

PAGE 3

CS 53/113-6