


# PUBLIC LAND CORNERS

SPRINGFIELD  
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 3W  
SECTION 34 CORNER E1  
COUNTY Douglas OREGON



**GLO SURVEY RECORD**

DATE: 1883 -- 1943  
CORNER Fir Post - Brass Cap

**PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)**

Found Brass Cap

**ACCESSORIES:**

	BEARING-	LINKS-	FEET-	
(1883) 6" Cedar	N62E	22	14.5	14" Cedar - Broken-down-rotted-axemarks
(1883) 12" Cedar	S72W	50	33.0	Rotted remains of cedar roots possibly of original PT
(1943) 11" Fir	S35E	5	3.3	12" Fir - dead - scribing visible
(1943) 22" Fir	S88W	36	23.8	28" Fir - Healed face

**SURVEY RECORD**  
DATE:

**PRESENT CONDITION:**

CORNER SET: Found brass Cap MAG. DECL.: 20°

**BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:**

BEARING-	FEET-	SURVEY -	
N62E	14.5	1883	14" Cedar
S65W	35.0	1883	Rotted remains of Cedar
S35E	3.3	1943-44	12" dead Fir
S89W	23.8	1943-44	28" Fir

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
28" Fir	S88W	23.6	1943	X	X	---
10" Hemlock	N11E	21.8	---	X	X	----

**IDENTIFIED ON PHOTO:**

**INFORMATION ON LOCATION OF CORNER AS NOW SET:**

GROUND COVER: Open  
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
SLOPE FACES (GIVE BEARING IN DEGREES) \_\_\_\_\_ ON MINUS (-) %

FROM CORNER | NORTH: - 8%  
| SOUTH: + 5%  
| EAST: -30% logged-residual trees  
| WEST: + 32% old growth

**WORK DONE FOR W. T. CO.:**

FIELD NOTES IN BOOK:

BY: Ellen M. Curvey DATE: September 23, 1959  
~~ENGINEER - SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

CS 53/113-7