

SPRINGFIELD
 SURVEY FILE


PUBLIC LAND CORNERS

MEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 25S RANGE 3W

SECTION 26 CORNER NE

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: 1943
 CORNER Brass Cap

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
24" Fir	<u>N73E</u>	<u>85</u>	<u>56.1</u>	<u>28" Fir - Face not open</u>
32" Fir	<u>S29E</u>	<u>54</u>	<u>35.6</u>	<u>32" Fir - Face not open</u>

SURVEY RECORD
 DATE: _____

PRESENT CONDITION: _____

CORNER SET: Brass cap set by GLO 1943

MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
<u>N73E</u>	<u>56.1</u>	<u>GLO 1943</u>	<u>Distance to center of tree. 28" Fir</u>
<u>S29E</u>	<u>35.6</u>	<u>GLO 1943</u>	<u>Distance to center of tree. 32" Fir</u>

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
<u>32" Fir</u>	<u>S29E</u>	<u>34.0</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>-</u>
<u>36" Fir</u>	<u>N63W</u>	<u>14.9</u>	<u>-</u>	<u>X</u>	<u>X</u>	<u>-</u>

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Oregon grape, salal

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S25°W ON MINUS (-) 28 %

NORTH: + 28% Old growth to East and West

SOUTH: - 28% 150' draw C-SE-old growth to East and West

EAST: Level 80' old growth North and South

WEST: - 15% 100' Creek C-SE old growth North and South

FROM CORNER 1

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Glen McChesney DATE: July 28, 1959
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY: _____

COPIES SENT TO: _____

SEAL

CS 53/113-8