


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 3 W
SECTION 24 CORNER NW
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
48" Fir	S 48 W	21.9	x	x	x	—
48" Fir	N 38 W	33.0	x	x	x	—
36" fir	S 35 E	30.1	—	x	x	—

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: OG Fir & hem Vine Maple & salal
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) S 20 W ON MINUS (-) 17 %

NORTH: +15

SOUTH: -15

EAST: 0

WEST: -5

FROM CORNER -

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

By: J. D. Titcomb DATE: 16 Nov 62
ENGINEER - ~~SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY: Don Jordan
Barrat Scott

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD				PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
DATE: <u>1883</u>				
CORNER: <u>Cedar post</u>				<u>Gone</u>
ACCESSORIES:				
BEARING-	LINKS-	FEET-		
36" Hem	N 50 E	18	11.9	
18" Hem	S 10 E	45	29.7	
48" Hem	S 50 W	33	21.8	
18" Hem	N 75 W	37	24.4	
GLO SURVEY RECORD				PRESENT CONDITION: <u>16 Nov 62</u>
DATE: <u>1943</u>				
2" Pipe with Brass cap				<u>found</u>
48" Hem stub	N 42½ E	18 lks		<u>gone</u>
24" Fir	S 11½ E	45 "		<u>scribe marks</u>
48" Fir	S 46½ W	33 "		<u>" "</u>
20" Fir	N 78 W	37 "		<u>" "</u>
40" Fir	N 12½ E	73 "		<u>face grown over</u>
40" Fir	N 37½ W	53 "		<u>" " "</u>

CORNER SET: _____ MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
S 47 W	22.3	1883	Measurements are to face
N 79 W	24.5	1883	" " "
N 37 W	33.5	1943	" " "
N 12 E	46.5	1943	" " "
S 12 E	29.2	1883	" " "

PAGE 1

CS 53/113-11

11