

SPRINGFIELD
SURVEY FILE


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 3 W

SECTION 34 CORNER "H" (CE 1/16)

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

| | BEARING | FEET | ORIG. B.T. | 'W' NAIL | PLATE | BRASS DISC |
|---------------|---------|------|------------|----------|-------|------------|
| 28" Red Cedar | S 55° W | 19.5 | --- | X | X | No. 2128 |
| 10" Red Cedar | N 35° W | 26.0 | --- | X | X | " |
| | | | | | | |

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Mostly 2nd growth Cedar with some Bigleaf Maple.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 75° E ON MINUS (-) 32 %

NORTH: -13°; 2nd growth Cedar and Hemlock; to East is in 1962 B.L. sale area to be logged in 1963.

SOUTH: 42% approx 75' to base of rock bluff bearing N 75° W & S 75° E; 2nd growth Cedar and Hemlock.

EAST: -26°; To North in same B.L. sale area.

WEST: 75% to base of bluff; 2nd Growth Cedar and Hemlock.

FROM CORNER -

GLO SURVEY RECORD

DATE: _____
 CORNER (no GLO Record)

ACCESSORIES:

| BEARING- | LINKS- | FEET- |
|----------|--------|-------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

SURVEY RECORD
 DATE: _____

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION: _____

CORNER SET: 1"x3/8" Iron Pipe Set

MAG. DECL.: 20°

(Set at point established by William S. Barnes Survey 6/63)

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

| BEARING- | FEET- | SURVEY- |
|----------|-------|---------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK: _____

BY: William S. Barnes DATE: 6/27/63

~~ENGINEER - SURVEYOR~~
 LAND AGENT

ASSISTED BY: _____

COPIES SENT TO: _____

UNDER THE SUPERVISION OF: _____

SEAL

PAGE 3

PAGE 1

CS 53/113-14

14