

SPRINGFIELD
 SURVEY FILE


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 3 W

SECTION 34 CORNER "F" (NE 1/16)

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
26" Red Cedar	S89° W	25.8	---	X	X	No. 2128
34" Douglas Fir	N30° W	30.5	---	X	X	"

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Mixed stand unlogged, 2nd Gr. Fir, Cedar & Hemlock

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) East ON MINUS (-) 11 %

NORTH: 16% mixed stand 2nd Gr. Fir, Cedar & Hemlock.

FROM CORNER | SOUTH: 10% about 15' to spring branch, flowing N 60° E; same mixed stand; all timber in SE 1/4 NE 1/4 to be logged 1963.

EAST: 11% 30' to same spring branch flowing N 60° E

WEST: 10% flattening into swampy area; uncut O.G. & 2nd growth Fir, Hemlock and Cedar.

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Tilt DATE: 6/27/63

~~ENGINEER-SURVEYOR~~
 LAND AGENT

ASSISTED BY: _____

UNDER THE SUPERVISION OF:

COPIES SENT TO: _____

SEAL PAGE 3

GLO SURVEY RECORD

DATE: _____
 CORNER (No GLO Record)

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

ACCESSORIES:

BEARING-	LINKS-	FEET-

SURVEY RECORD

DATE: _____

PRESENT CONDITION: _____

CORNER SET: 1"x36" Iron Pipe set MAG. DECL.: 20°

(Set at point established by William S. Barnes Survey 6/63)

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS 53/113-15

91