PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 25 S RANGE 4 W

SECTION 3 CORNER W 1/16 = "B"

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1" aluminum pipe by single proportionate measurement MAG. DECL.:

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
12" Hemlock	S 51 W	65.7	-	X	X	#2149
10" Hemlock	N 75 W	33.7	-	X	X	"

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Hazelnut

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) South ON MINUS (-) 10 %

FROM CORNER –

NORTH: + 35%

SOUTH: - 10% 50' to dirt road

EAST: + 5%

WEST: level 100' to dirt road

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Tilt DATE: February 4, 1964
ENGINEER – SURVEYOR

ASSISTED BY: Robert Barta

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS 53/113-16

91