SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 26 S RANGE 2 W

SECTION 8 CORNER CS 1/16

COUNTY Douglas OREGON

GLO SURVEY RECORD

DATE: -----

CORNER -----

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

SURVEY RECORD

M. C. Ramsey
R.S. No. 404

DATE: 1960

I. Pipe 1" x 3' at Corner from which

BT's:
14" D. Fir S 70° W 8 lks (5.3')
18" D. fir N 10° W 30 " (19.8')

PRESENT CONDITION:

Corner pipe good condition

Both BT's in good condition; plainly scribed.

From above identified CORNER: I find as follows: MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
S 70° W	5.1	1960	M.C. Ramsey BT; measured to face; 12" tree
N 10° W	18.8	1960	" " "; " " " ; 14" "

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	~~GRIG~~ B.T.	"W" NAIL	PLATE	BRASS DISC
44" D. Fir	N 30° E	41.2	--	X	X	--
12" D. Fir	S 70° W	5.1	Ramsey 1960	X	X	--
14" D. Fir	N 10° W	18.8	Ramsey 1960	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 45° W ON MINUS (-) 55 %

FROM CORNER I

NORTH: - 43%; Uncut mixed stand OG D. Fir and large 2nd Gr. D. Fir; Ramsey call N 1° 37' E 20.75 Ch. to C 1/4 Cor.

SOUTH: + 15%; Uncut mixed stand OG D. Fir and large 2nd Gr. D. Fir to West; logged 6-8 years to East with scattered residual 2nd Gr. D. Fir; Good blazed line Ramsey call S 1° 37' W 20.75 Ch to 1/4 Cor.

EAST: + 60%; Good blazed line; Ramsey calls N 86° 54' E 19.98 Ch to SE 1/16 Cor.

WEST: - 66%

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L Tait DATE: 6/22/61
~~ENGINEER - SURVEYOR~~
Land Agent

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/114-6