


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 26 S RANGE 3 W
 SECTION 2 CORNER C N 1/16 "F"
 COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE: _____ MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
24" White Fir	N 17° W	17.7	W.T.	X	X	
38" (failed to record)	S 54° W	34.5		X	X	

IDENTIFIED ON PHOTO: 2

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) 1/2 %

NORTH: _____
 SOUTH: _____
 EAST: _____
 WEST: _____

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Allen McCleary DATE: 5/18/57
 ENGINEER/SURVEYOR

UNDER THE SUPERVISION OF: _____

ASSISTED BY: _____

COPIES SENT TO: _____

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

CORNER	DATE:	
ACCESSORIES:		
BEARING-	LINKS-	FEET-

W.T.Co. - Klahanee SURVEY RECORD
 DATE: 8/20/1943

PRESENT CONDITION: _____

20" White fir N 17° W 17.9' 24" white fir - plate but no "W" nail

CORNER SET: Found post in place MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CSS3/115-1