

# PUBLIC LAND CORNERS


SPRINGFIELD  
**SURVEY FILE**

MEYERHAEUSER TIMBER COMPANY  
 SPRINGFIELD BRANCH

TOWNSHIP 26 S RANGE 3 W

SECTION 2 CORNER NE 1/16 "P"

COUNTY Douglas OREGON



**GLO SURVEY RECORD**

PRESENT CONDITION - (DESCRIBE FULLY -  
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

DATE: \_\_\_\_\_  
 CORNER \_\_\_\_\_

**ACCESSORIES:**

BEARING-	LINKS-	FEET-

**WTCO. - Klahanee SURVEY RECORD**

PRESENT CONDITION: \_\_\_\_\_

DATE: August, 1943

Post  
30" Fir - N 27° E - 31.31

Down  
38" Fir - Plate but no "W" nail

CORNER SET: Set post from Weyerhaeuser Timber Co. MAG. DECL.: 20°

**BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:**

BEARING-	FEET-	SURVEY-
<u>N 27° E</u>	<u>31.3</u>	<u>WTCO.</u>

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
<u>38" Fir</u>	<u>N 27° E</u>	<u>31.2</u>	<u>W.T.</u>	<u>X</u>	<u>X</u>	
<u>12" Incense Cedar</u>	<u>S 41° E</u>	<u>10.0</u>		<u>X</u>	<u>X</u>	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: \_\_\_\_\_

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) \_\_\_\_\_ ON MINUS (-)    %

NORTH: \_\_\_\_\_

SOUTH: \_\_\_\_\_

EAST: \_\_\_\_\_

WEST: \_\_\_\_\_

FROM CORNER -

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: \_\_\_\_\_

BY: Allen McChesney DATE: 5/18/58  
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY: \_\_\_\_\_

COPIES SENT TO: \_\_\_\_\_

CS 53/115-3