


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 26 S RANGE 3 W
SECTION 2 CORNER NW
COUNTY Douglas OREGON



GLO SURVEY RECORD				PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)	
DATE: 1943					
CORNER U.S. GLO Brass cap set from original NE and SW Bts.				Found	
ACCESSORIES:					
BEARING-	LINKS-	FEET-			
22" Fir Stub	N 69 E	35	23.1	22" Fir stub - faint bark scribing visible	
36" Fir	S 45 W	10	6.6	Face healed over on 42" Fir	
10" Inc. Cedar	N 20 1/2 E	45	29.7	10" Incense Cedar - Scribing visible	
22" White Fir	S 67 E	41	27.1	22" White Fir stub 8' high - Face	
12" Inc. Cedar	N 62 1/2 W	19	12.5	14" Incense Cedar - Scribing visible	
SURVEY RECORD DATE:				PRESENT CONDITION:	

CORNER SET: Brass cap as set by 1943 GLO (Dependent) MAG. DECL.: 20°
Resurvey

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:			
BEARING-	FEET-	SURVEY-	
N 69 E	23.1	Original	Bearing and distance to face
S 55 W	6.6	Old-New	Bearing not S 45 W as per 1943 GLO record
N 20 E	29.7	1943	Bearing and distance to face
S 67 E	27.1	1943	Bearing and distance to face
N 60 W	12.1	1943	Bearing and distance to face

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	W' NAIL	PLATE	BRASS DISC
46" Fir	N 1 E	21.4	-	X	X	-
24" x 8" White Fir stub	S 67 E	27.0	X	X	X	-
42" Fir	S 60 W	5.7	X	X	X	-
14" Incense Cedar	N 59 W	12.1	1943	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Old growth to NE, SW, and NW; recently logged to SE.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) ON MINUS (-) 30%

FROM CORNER -
NORTH: + 10%
SOUTH: - 10%
EAST: - 30%
WEST: + 28%

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: *Shawn's Change* 3/11/65
ENGINEER SURVEYOR
LAND AGENT

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

**FILED
RECEIVED**

OCT 19 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

SEAL PAGE 3

S. File No. 53/115-4

336
120