


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 26 S RANGE 3 W
 SECTION 24 CORNER C 1/2
 COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: _____
 CORNER _____

ACCESSORIES:

BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION:

Being temporary point only for cutting,
 Lester Calder ordered destruction of pipe and
 references.
 Removed "W" nail and plate.
 " " " " "
 " " " " "
 " " " " "

Youngs
 W.T.Co. - Youngs Bay SURVEY RECORD
 DATE: 1952

3/4" Pipe
 16" Hem. N 55° E 21.1
 50" Fir N 61° W 14.5
 3" Hem. S 63° W 2.6
 4" Hem. S 66° E 6.5

CORNER SET: _____ MAG. DECL.: _____

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

ACCESSORIES ADDED THIS DATE: _____

MAGNETIC DECLINATION: _____

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) %

NORTH: _____
 SOUTH: _____
 EAST: _____
 WEST: _____

FROM CORNER -

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Glen McCreary DATE: _____
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY: _____

COPIES SENT TO: _____

CS 53/115-6