


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH
 TOWNSHIP 26S RANGE 3W
 SECTION 24 CORNER CK "I"
 COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: _____
 CORNER _____

ACCESSORIES:

BEARING-	LINKS-	FEET-

SURVEY RECORD
DATE: _____

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION: _____

CORNER SET: 1" Conduit pipe set at intersection N-S and E-W center lines. See Page 2
 MAG. DECL.: _____

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -

ACCESSORIES ADDED THIS DATE: _____

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
30" Hemlock	N38E	16.0	--	X	X	--
30" Hemlock	S32E	18.0	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Corner falls in creek course N65^W
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) _____ %

FROM CORNER -
 NORTH: old growth to East, 1959 relog to West
 SOUTH: logged to East - 1959 relog to West
 EAST: old growth to North, logged to South
 WEST: 1959 relog to North and South

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Edmund McCreary DATE: August 25, 1959
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF: _____

ASSISTED BY: _____

COPIES SENT TO: _____

CS 53/115-7