


# PUBLIC LAND CORNERS

SPRINGFIELD  
**SURVEY FILE**

**WEYERHAEUSER TIMBER COMPANY**  
**SPRINGFIELD BRANCH**  
 TOWNSHIP 26S RANGE 3W  
 SECTION 24 CORNER N1/16 "C"  
 COUNTY Douglas OREGON



MAGNETIC DECLINATION 20°

ACCESSORIES ADDED THIS DATE:

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
20" Fir Stump	S88E	31.1	WTCO Youngs Bay	Previous	X	previous
20" Fir	N21E	36.3	"	"	X	"

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal  
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
 SLOPE FACES (GIVE BEARING IN DEGREES) North ON MINUS (-) 24 %

NORTH: - 24% 60' springbranch C-N20E old growth  
 SOUTH: + 26% Current relog to East  
 EAST: + 9% 75' ascent steepens - current relog South  
 WEST: Level 40' old growth to North and South

FROM CORNER

GLO SURVEY RECORD

CORNER DATE: \_\_\_\_\_

ACCESSORIES:

BEARING-	LINKS-	FEET-

WTCO-Youngs Bay SURVEY RECORD DATE: 1950-1951

2" Cedar Post	Found
18" Fir - S89E 31.1	20" Fir Stump Found discs & "W" nails only.
18" Fir N24E 36.3	20" Fir

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION: \_\_\_\_\_

CORNER SET: 2" Cedar Post set by WTCO and Youngs Bay MAG. DECL.: 20°

1950-51 Survey

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
S88E	31.1	1950-51
N21E	36.3	1950-51

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: H. W. McChesney DATE: August 18, 1959  
~~ENGINEER - SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL PAGE 3

CS 53/115-9