SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 26S RANGE 3W

SECTION 24 CORNER N¼

COUNTY Douglas OREGON

GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Found no evidence of original
Corner. The spot has been covered by
an old burn

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: By single proportionate method set MAG. DECL.: Not known

3" square yew post.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION Not Known

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
32" Fir	N22W	29.9	--	X	X	--
48" I. Cedar	N80E	36.1	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER:

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) ON MINUS (–) %

FROM CORNER –

NORTH:

SOUTH:

EAST:

WEST:

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: C. Price DATE: August 1953

~~ENGINEER – SURVEYOR~~

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS 53/1157D