

PUBLIC LAND CORNERS


SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 26S RANGE 3W

SECTION 24 CORNER NE

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION _____

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
Not Referenced						

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) %

NORTH: _____
SOUTH: _____
EAST: _____
WEST: _____

FROM CORNER -

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

CORNER DATE: _____

Found Stone - 3 notches on North and 3 notches on South sides.

ACCESSORIES:

BEARING-	LINKS-	FEET-
N E		
S E		
S W		
N W		

Evidence found

Evidence found

Snag

5' stub

SURVEY RECORD DATE: _____

PRESENT CONDITION: _____

CORNER SET: original stone as found

MAG. DECL.: ---

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

By: Curtis Price DATE: 1951
~~ENGINEER - SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY: _____

COPIES SENT TO: _____

SEAL PAGE 3

PAGE 1

SEE 1965 RENEWAL NOTES CSS3/115-11