


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 26S RANGE 3W
 SECTION 24 CORNER NW
 COUNTY Douglas OREGON



MAGNETIC DECLINATION ---

ACCESSORIES ADDED THIS DATE:

| | BEARING | FEET | ORIG. B. T. | "W" NAIL | PLATE | BRASS DISC |
|-----------|---------|------|-------------|----------|-------|------------|
| 28" Cedar | S36E | 37.5 | -- | X | X | X |
| 32" Fir | N65E | 40.4 | -- | X | X | X |
| 14" Fir | N84W | 31.6 | -- | X | X | X |
| 24" Fir | S22W | 57.5 | -- | X | X | X |

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) %

NORTH: _____
 SOUTH: _____
 EAST: _____
 WEST: _____

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: C Price DATE: August 1951

UNDER THE SUPERVISION OF:

~~ENGINEER - SURVEYOR~~

ASSISTED BY: _____

COPIES SENT TO: _____

SEAL PAGE 3

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY -
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)

DATE: _____
 CORNER _____

ACCESSORIES:

| | BEARING- | LINKS- | FEET- | |
|-----------|----------|--------|-------|--------------------|
| | NE | | | Burned Cedar Shell |
| 30" Cedar | S82E | 19 | | Good Condition |
| | SW | | | Destroyed by fire |
| | NW | | | Burned Cedar Shell |

SURVEY RECORD
 DATE: _____

PRESENT CONDITION: _____

CORNER SET: Set a 2 1/2" square cedar post S82E 19 lks from MAG. DECL.: ---
from the identified BT

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

| BEARING- | FEET- | SURVEY - |
|----------|-------|----------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

PAGE 1

SEE 1965 RENEWAL NOTES CS 5311572