


# PUBLIC LAND CORNERS

SPRINGFIELD  
**SURVEY FILE**

**WEYERHAEUSER TIMBER COMPANY**  
**SPRINGFIELD BRANCH**  
 TOWNSHIP 26S RANGE 3W  
 SECTION 24 CORNER S $\frac{1}{2}$   
 COUNTY Douglas OREGON



### GLO SURVEY RECORD

DATE: 1882  
 CORNER Cedar Post

PRESENT CONDITION - (DESCRIBE FULLY -  
 USE PAGE 2 IF NEEDED FOR EXPLANATION.)  
No Trace

### ACCESSORIES:

	BEARING-	LINKS-	FEET-	
20" Fir	N40E	23	15.2	36" Fir - Bark scribed
12" Fir	S10E	15	9.9	26" dead Fir - scribing visible

County   SURVEY RECORD  
 DATE: 1957

PRESENT CONDITION:  

Brass Cap	Found
10" S. Pine - S78 $\frac{1}{2}$ E 31.4'	10" S. Pine scribed "CS S25 BT"
12" Red Fir - N82E 3.0'	12" Fir scribed "CS S24 BT"

CORNER SET: Brass Cap Set by Douglas County MAG. DECL.: 20°

### BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N9E	16.4	GLO	Distance to scribing on bark
S11E	10.3	GLO	Distance to face
S80E	31.4	CS	Distance to face
N85E	2.2	CS	distance to lower face

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
36" Fir	N7E	16.2	X	X	X	--
12" Fir	N85E	2.1	CS	X	X	--

IDENTIFIED ON PHOTO:

### INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: North edge grassy opening  
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
 SLOPE FACES (GIVE BEARING IN DEGREES) S35W ON MINUS (-) 55 %

NORTH: + 64% scattered old growth and red typo fir  
 SOUTH: - 55% down grassy opening  
 EAST: + 33% 40' to edge grassy opening  
 WEST: - 26% across grassy

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:  

BY: Glen M. Chiswick DATE: August 18, 1959  
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY:  

COPIES SENT TO:  

SEAL PAGE 3

CS 53/115-13