


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH



TOWNSHIP 26S RANGE 3W
 SECTION 24 CORNER CN1/16 "R"
 COUNTY Douglas OREGON

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
42" Fir	N62W	23.8	--	X	X	--
4" Hemlock	S15E	1.0	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: SALAL, DOGHAIR HEMLOCK
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) N55E 10 % ON MINUS (-)

NORTH: - 6% old growth to East and West
 SOUTH: + 6% 30'; + 26% old growth to East - 1959 relog to West
 EAST: - 10% old growth to North and South
 WEST: + 16% old growth to North, 1959 relog to South

FROM CORNER

GLO SURVEY RECORD

CORNER DATE: _____

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

W.Co.-Youngs Bay SURVEY RECORD
 DATE: 1950-1951

PRESENT CONDITION:

Stake
 32" Fir N34E - 8.8' Disc, "W" nail and plate
 48" Fir N76W - 26.1 Disc, "W" nail and plate

Being temporary point only for cutting I destroyed stake and accessories.

CORNER SET: 1" pipe set by single proportion - see page 2. MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Glen McChesney DATE: August 25, 1959
~~ENGINEER SURVEYOR~~

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

CS 53/115-18