

Renew W. $\frac{1}{4}$ / 519 T215 R10W

Fd. 1919 & LO BRASS CAP BROKEN OFF
OF CONCRETE FILLED I.P. IN PLACE &
B.T.S AS FOLLOWS -

11" NOW 34" FIR N. 31° E. 29 $\frac{1}{2}$ FT.

alive - shows good SCAR - we do not open.

Rescribe " $\frac{1}{4}$ 519 CS BT"

18" NOW 32" FIR S. 11° E. 77 $\frac{1}{2}$ FT.

alive - shows good SCAR - we do not open

& COR. POINT IN PLACE OF OLD PIPE

SET 1" I.P. & BRASS CAP MKD. "COUNTY
SURVEYOR'S OFFICE 1968 T215

R11W $\frac{1}{4}$ / 519 R10W" & DEPOSIT

OLD COR. MATERIAL ALONG SIDE BRASS CAP,
& MK. NEW B.T. -

20" D. FIR N. 75° E. 63 $\frac{1}{2}$ FT.

MKD. " $\frac{1}{4}$ 519 CS BT" - NO OTHER TREES CLOSE

THIS COR. LIES ON VERY STEEP

SOUTHERLY SLOPE 16 FT. N. OF SMALL

CREEK COURSE EAST - ACROSS CREEK

THERE IS MOUTH OF SMALL Ravine.

July 15, 1968

N. R. Tray

N.R.T.
S.M.
V.P.

#25 O.W. J.W.B.

54-12-11

C.S. No. 53/1-16