


Section 13 Twp 26 S Rge 2 W W

Date: 3/04/66



How was corner identified? Square post set in ground

Condition of corner: Poor

N.F. 3/5/66

Best route to reach corner: Paris Ranch Road

U.R.T.
M.S.
J.H.

U.R.T. 244

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size	2 1/2" N.F.	1/4" 5/8"	T265 R1W	
Dist. & Bearing				
Condition of Scribe	3/5/66	<u>U.R.T.</u>		
Original or Resurvey				
Appearance of B.F.		1/6	T26-1	
Exp. Marks, etc.	N.F.	1/7		

No BT's found. Needs iron pipe + cap set. BTs marked.

B. J. A.
Signed
C.S. File No. 54/7-72