

Renew $\frac{1}{4}$ cor. S 17 / S 16 T 25 S R 7 W

Fd. O.B.T.s as follows -

Orig. 20" now 40" Fir S. 46° E. 42 $\frac{1}{2}$ ft.

Now stump - find Probable Axehk. on
BARK. -

Orig. 10" now 21" Fir S. 38° W. 30 $\frac{1}{2}$ ft. (slope)

alive - previously opened E shows " $\frac{1}{4}$ "

scribe - at cor. point set 1"

IN. & BRASS cap MKd. "COUNTY

SURVEYORS OFFICE 1970 T 25 S

$\frac{1}{4}$ S 17 / S 16 R 7 W" & MK. New BTs -

14" D. Fir N. $60\frac{1}{2}^{\circ}$ W. 13 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ S 17 CS BT"

12" D. Fir N. 70° W. 10 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ S 16 CS BT"

From cor. as set by us we

find small squared post with

Hxk tack in top bearing N. 38° E

4 $\frac{1}{2}$ ft.

This cor. lies on steep

N.E. slope approx. 75 $\frac{1}{2}$ ft. South

~~of~~ creek course Easterly

May 13, 1970

VRT
JWB

#97 W. R. Tracy

D.H.
J.W. 19.

C. S. File No. 5410-16