

Review $\frac{1}{4}$ $\frac{517}{520}$ T235 RBW

Fd. ove BT as follows -

ORIG. 12" Now 28" FIR N. 30° W, 59 $\frac{1}{2}$ ft.

We open & find PARTIAL "S" & Notch at

Bottom of face. BT is Down. No

Trace other ORIG. BT. We set 1"

I.P. & BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1965 T235

$\frac{1}{4}$ $\frac{517}{520}$ RBW" & MARK New BTs -

16" D. FIR N, 8° E, 36 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ S 17 CS BT"

6" D. FIR S, 3° E, 15 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ S 20 CS BT"

This COR Lies on S. Edge of
Jeep Road Bear S. 55° E.

June 24, 1965

WRT.
T.C.

~~FILED~~

RECEIVED

JUN 24 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Q 428
+ X

C. S. File No. 54/12-34