

Set Witness COR. to $\frac{1}{4}$ $\frac{57}{518}$ T235 R8W

Fd. ORIG. 40' Now 54" D.FIR COR. Tree
No scribe found & BT's as follows -

ORIG. 14" Now 18" Maple N. 25° E. 12 $\frac{5}{8}$ ft.
we open - center rotted away - no scribe
found.

orig. 12" Now 18" D.FIR S. 58° W. 19 $\frac{3}{8}$ ft.
we open & find poor $\frac{1}{4}$ 5" on Burned
face. Since distances E, or W. would

be to large to set wit. COR. we Run
North 55° ft. & set 1" I.P. & BRASS
cap for Wit. COR., MKd. COUNTY

SURVEYORS OFFICE 1966 T235
WIT. COR. $\frac{1}{4}$ $\frac{57}{518}$ 55 FT. S. TO COR.

R8W" & MK. new BT's -
23" D.FIR N. 76° E. 71 $\frac{5}{8}$ ft.
MKd. WC $\frac{1}{4}$ 57 CS BT"

23" D.FIR S. 74 $\frac{1}{2}$ ° E. 52 $\frac{3}{8}$ ft.
MKd. WC $\frac{1}{4}$ 518 CS BT"

Actual COR. Location & B.T.'s will
be destroyed by Road Const.
Wit. COR. lies on steep South Slope.

April 20, 1966

V.R.T:
M.S.
J.H.

OX#35

C. S. File No.

54/12-36