

Renew Sec. Cor. $\frac{512}{513}$ T235 R8W

from the Closing Cor. of Sec.'s 11 & 14

We measure North 1103 ft. & find

2 badly Broken Sandstone with 2 notches on one piece & possible notch on edge.

From this point we find the following

B.T. -

orig. 30" now 50" Fir S. 1°W, 16⁵/₈ ft.

2 live - previously opened & rehealed.

We open & find axe notch & burned face with possible scribe mk. Ring count

100+ years to face - opened 70+ years

ago. We find no other B.T.s - set.

1" I.P. & BRASS CAP MKD. "COUNTY

SURVEYOR'S OFFICE 1967

T235 $\frac{512}{513}$ R8W " & MK. new B.T.s

12" Maple N. 78°E, 26⁸/₈ ft.

Mkd. "T235 R8W 512 CS BT"

5" D. Fir S. 25¹/₂°E, 27⁸/₈ ft.

Mkd. "S 13 CS BT"

This cor. lies on small Bench

1103 ft. N. of Closing Cor.

of Sec.'s 11 & 14.

Feb. 8, 1967

FEB 8 1967

J.H.
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C.S. File No. 54712-55 J.W.B.