

18/17
Renew Sec. Cor. 19/20 T235 R4W

Ed. 1 3/4" Axle shaft 14" above ground at
fence cor. going N. & W, ME, BT Now

STump pushed out of place. we find
Other BT's Recorded in Renewal # 33

OK. & Listed Below -

20" R. Fir S. 71° E. 46⁹ ft.

Scribe visible -

20" R. Fir N. 69° W. 31° ft.

Scribe visible.

We MK New BT's -

17" D. Fir S. 84° W 80° ft.

Mkd' "T235 R4W S 19 CS BT"

8" R. cedar N. 2° E. 262° ft

Mkd. "T235 R4W S 17 CS BT"

axle shaft is Mkd. " 18 17 "
19 20 "

Oct 22, 1965

U.R.T.
MS.
J.L.

FILED
RECEIVED

OCT 22 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 54/16-9

#106
+X