

Removal

S18  
S19

T213 R4W

11" Fir	Dead	S19W	62	OST
Shaws	good	sear		
16" Fir	DOWN	N91W	112	OST
8" cedar	gone	N87W	352	
17" Laurel	gone	S16W	192	
8" cedar	Now 11"	N68E	222	
Scribed	1/5 1B	BT-1		

Found Iron Rod out of ground:

Removal:

Set Brass cup at 1/4 cor MAP,  
county Surveyors office

T213 R4W

1 S18  
1 S19

1966

Set Iron Rod along side Brass cap  
New Bearing Tree

40" D. Fir		West	802
Scribed	1/5 19	CS BT	

Removal #85

~~2-25-66~~  
~~CES~~  
~~WY~~

\*#122

C. S. File No. 54-20-20

DIETZGEN NO. 385-6