

Renewal

$\frac{33}{7}$

T315
T325 PAW

12" Fir NOW 19" N9E 85"
Shawl good Secs.

I find this Bearing to be N4E

18" Cedar NOW 22" S42 1/2 W 34 3/4
Scribe visible \$ 54 BT

NOTE: BRASS CAP SET BY COV.
NOT FOUND.

Renewal

Set $\frac{3}{7}$ " Iron Rod at floor
in crack bed.

Set Brass cap for W. T. Cox M&R,
County Surveyors office

T315

W.C.

$\frac{1}{1}$ 25" West R
 $\frac{1}{1}$ $\frac{33}{7}$ W

T325

1964

New RTS.

9" D.F. H Scribed W.C. N29W 30 3/4
S 33 CS BT

23" D.F. H Scribed W.C. S45 1/2 E 6 1/2
S 14 CS BT

3-3-64
J.M.C.
W.C.S.

#134 T31-4
J.B. #96-32-4

C.S. File No. 54/20-25

DIETZEN NO. 388-6

X