

Revised 13/18 T 315 R 6-5 W
24/19

Found:

1 $\frac{1}{2}$ " Iron Pipe
OAK
10" Live oak N 43 E 10/18 26 $\frac{1}{2}$
opened for Scribe "BT"
8" Laurel (Dead) N 41 W 11/18 27 $\frac{1}{2}$
opened for parts of Scribe
Marks

From Kings Iron Pipe I Find

10" Live oak N 47 E 24 $\frac{1}{2}$
OAK Scribe "BT"
8" Laurel N 44 E W 28 $\frac{1}{2}$
OAK Scribe Marks
5" Fir now 6" N 44 E 28 $\frac{1}{2}$
Pitched over Scribing
11" Live oak now 12" S 61 E 35 $\frac{1}{2}$
Scribed T 315 R 6 W 519 BT
10" Live oak now 11" S 46 W 15 $\frac{1}{2}$
Scribed T 315 R 6 W 324 BT

Revised:

Set Brass cap at Sec. cor MRD,
County Surveyors office

T 315
R 6 313/518 R 5
W 524/519 W

1966

New Bearing Trees:

Kings 1 $\frac{1}{2}$ " Iron Pipe N 43 E 1 $\frac{1}{2}$

6" Fir N 44 E 30 $\frac{1}{2}$
Shows good Scribing

12" Live oak S 65 E 36 $\frac{1}{2}$
Shows good Scribing

11" Live oak North 25 $\frac{1}{2}$
Scribed T 315 R 6 S 13 C 5 BT

R6 11" Live oak S 42 W 14 $\frac{1}{2}$
Shows good Scribing

Revised # 27

G-2-66
C.S. No. 54/28/29