

Renewal

525/530

T313 R6-SW

Found:

39" Fir Stump S55E 112
Scribed T313 R6-SW 7 5 30 BT

36" Fir snag N82W 38L
Scribed T313 R6-W 7 5 45 BT

As Noted car Falls in creek
Therefore no car was set.

Renewed:

Set Brass cap for Wit con MKL

County Surveyors Office

T313
R W.C. R
6 25th Ft North S
W 70 W
7 525/530
1966

New Bearing Trees

70" Fir Stump S40E 123
Scribed W.C. 7 5 30 CS BT

7" Alder S80W 190
Scribed W.C. 7 5 25 CS BT

Brass cap lies about 25^{ft} South of stream & 28^{ft} West of Spring. W.C. H.

Renewal 57

5-1-66
J. W. B.
D. C. B.

#86 R6SW

#93

* O. K. J. W. B.

C. S. File No. 54/25-31

DIETZGEN NO. 385-S