

Reverval

16
21

T285 B1W

Toward

OBT's

18" D. Fir New stump

S15W

92

Tree has been opened

Scribe marks visible

18" D. Fir New stump

N50E

62

Stumps good scar

New P.T.

16" D. Fir New 14"

S86E

87

Pitaked over fence

1/4 S21 87

Reverval

No car falls in new Rd set with
car 50° East

Set Brass cap at wt cor MKD.

County Surveyors office

T285 B1W

wt cor. 50° West to

1/4 16
21

1967

New Bearing Traces

15" D. Fir

S16W

11⁰

Scribed w.c. 1/4 S21 63 BT

11" D. Fir

N157E

10⁰

Scribed w.c. 1/4 S16 65 BT

Other BT to original car becomes

16" D. Fir

S80E

35⁰

Scribed 1/4 S21 BT

Note:

This car will fall approx 70° East
of Rd. Rd. Not yet built
Road S.A.R. 171 + 36.

10-37-67
~~10-37-67~~

C. S. File No.

5426-12