

Review $\frac{1}{4}$ $\frac{516}{521}$ T255 R3W

Fd. G.O. BRASS CAP MKD. " $\frac{1}{4}$ $\frac{516}{521}$ 1943"

with steel fence post set along side, both B.T.s destroyed by Logging - we MK. New B.T.s -

7" D. FIR S. $9\frac{1}{2}$ ° E. 33 ° FT.
MKD. " $\frac{1}{4}$ 521 CS BT"

9" D. FIR N. 75 ° E. $9\frac{8}{16}$ FT.
MKD. " $\frac{1}{4}$ 516 CS BT"

13" D. FIR S. 77 ° W. 16 ° FT.
MKD. " $\frac{1}{4}$ 521 CS BT"

This cap lies on N. Edge of old unusable Log Rd. course E-W, approx. 225 ft. East of main Hinkle Crk. Rd.

August 15, 1966

V.R.T.
J.H.

(Handwritten signature)
FILED
RECEIVED

AUG 15 1966

#109

*

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

C.S. No. *521/22*

42