

Renew $\frac{1}{4}$ 511 / 512 T255 R3W

Fd. G.L.O. BRASS CAP MKD " $\frac{1}{4}$ 511 / 512

1943" Bent over & Buried. We dig up

BRASS cap & straighten pipe & Reset.

All B.T.s destroyed by logging & Fire.

scribe visible on 40" FIR (STAMP)

574 $\frac{1}{2}$ ° E. 29 $\frac{3}{4}$ ft - we MK.

New B.T.s -

5" D. FIR S. 40° W. 19 $\frac{1}{4}$ ft.

MKD. " $\frac{1}{4}$ 5 11 CS BT"

24" cedar (STAMP) S. 67° E. 53 $\frac{3}{4}$ ft.

MKD. " $\frac{1}{4}$ 5 12 CS BT" (7° ft. high)

also steel fence post set along

side BRASS CAP - COR. Lies in

old Logged & Burned area - growing

up to small FIR & Hemlock in heavy

Greenswood & willow brush.

July 27, 1966

V.R.T.

J.B.

J.H.

FILED

RECEIVED

JUL 27 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

*98
O.K. J.W.B.

C.S. File No. 54/27-60