

Review  $\frac{1}{4}$  COR  $\frac{S26}{S35}$  T23S R2W

Fd. ORIG. COR. Stone in place

& MKd. " $\frac{1}{4}$ " & OBTs 2s follows

ORIG 36" Now 38" FIR N,  $42^{\circ}$ E, 21 $\frac{1}{2}$ ft.

alive - Shows good SCAR -

ORIG. 6" Now 7" Hemlock S,  $45^{\circ}$ E, 13 $\frac{9}{10}$ ft.

Now 5 1/2" - open & shows " $\frac{1}{4}$ S BT"

SCRIBE. at COR point in

place of stone set 1" IP.

& BRASS COP MKd. "COUNTY

SURVEYOR'S OFFICE 1969

T23S  $\frac{1}{4}$   $\frac{S26}{S35}$  R2W" & MK.

New B.T.s -

7" Hemlock N,  $49^{\circ}$ E, 23 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$  S26 CS BT"

11" Hemlock S,  $39^{\circ}$ E, 21 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$  S35 CS BT"

This COR. lies on westerly  
slope approx 60 ft. west of  
CREEK 4 $\frac{1}{2}$ ' wide course N.

July 7, 1969

W. B. Tracy

W.R.T.  
V.D.P.

OK.  
5/27/69

#161

54/27-101