

Renew Sec. Cor. RW  $\frac{525}{536}$   $\frac{530}{531}$  T245

Fd. OBTs as follows -

Orig 6" Now 14" Fir S.  $34^{\circ}E$ , 14<sup>24</sup>

2 live - shows good scar - we Rescribe

"T245 RIE 531 CS BT"

Orig. 12" cedar Now 20" Hemlock S,  $77^{\circ}W$ ,

23<sup>8</sup> ft. - Now STAMP shows good  
SCAR-

Orig. 24" Now 30" cedar N,  $40^{\circ}W$ , 42<sup>9</sup> ft

3 live - scribe MKs visible on nearly  
healed blaze - we Rescribe "T245 RW  
525 CS BT" - OBT. To NE Down -  
shows scar - 2<sup>nd</sup> COR point set

1" I.P. & BRASS cap MKd. "COUNTY

SURVEYORS OFFICE 1970 T245

RW  $\frac{525}{536}$   $\frac{530}{531}$  RIE " & MK. New BTs

15" Hemlock N.  $82^{\circ}E$ , 39<sup>9</sup> ft,

Mkd. "T245 RIE 530 CS BT"

9" cedar S,  $8^{\circ}W$ , 23<sup>3</sup> ft,

Mkd. "T245 RW 536 CS BT"

This cor lies near bottom  
of N. slope approx 40 ft. FROM  
Flat Bench To North.

May 12, 1970

L.A.I

V.D.P.

#90-T245 RW N.T.P.


C.S. File No. 54/27-207

Section ~~25~~, 36  
30, 31

Twp 24S Rge 1W N  
Twp 24S Rge 1E

Date: 3/20/86

How was corner identified? FD BRASS CAP



**FILED  
RECEIVED**

Condition of corner: GOOD

APR 1 1980

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE

Best route to reach corner: None

Quadrant	(NB)	(NW)	(SE)	(SW)
Species & Size	Hemlock 18"	Cedar	Cedar	Hemlock Stump
Dist. & Bearing	N 82° E 39.9 FT	N 40° W 42.9 FT	N 82° E 23.3 FT	29" S 77° W 32.8 FT
Condition of Scribe	Closed	semi Closed	OPEN	Closed
Original or Resurvey	Resurvey	Original	Resurvey	Original
Appearance of B.T.	Good	Good	Good	Good
Tags, Marks, etc.	Good	Good	Good	Fs. BT TAGS

~~CELEBRATION SALE~~

Signed  
Steven Anderson